TOWN OF LAKE COWICHAN



Public Works and Environmental Services Committee Tuesday, March 17th, 2020 at 6:00 p.m. – Council Chambers

AGENDA

1. CALL TO ORDER

INTRODUCTION OF LATE ITEMS (if applicable)

2. APPROVAL OF AGENDA

3. BUSINESS ARISING AND UNFINISHED BUSINESS

- (a) Superintendent, Public Works and Engineering Services re: WTP Update
- (b) Ongoing Items Still Being Addressed:
 - (i) CLEC Water System-Update.
 - (ii) Updating of Signage.

4. DELEGATIONS AND REPRESENTATIONS

5. CORRESPONDENCE

6. VERBAL COMMENT FROM THE PUBLIC ON A SUBSEQUENT ITEM ON THE AGENDA– (maximum 3 minutes per speaker and maximum time allotted 15 minutes)

7. **REPORTS**

- (a) Superintendent, Public Works and Engineering Services re: Summary Report for Feb/March 2020.
- (b) Superintendent, Public Works and Engineering Services re: Roads-Capital Plan.
- (c) Superintendent, Public Works and Engineering Services re: Sidewalks-Capital Plan.
- (d) Superintendent, Public Works and Engineering Services re: South Shore Bus Shelter Replacement.
- (e) Superintendent, Public Works and Engineering Services re: Sewer Plan 2020.
- (f) Superintendent, Public Works and Engineering Services re: Town Waters Distribution Network.

8. **NEW BUSINESS**

None.

9. NOTICES OF MOTION

10. PUBLIC RELATIONS ITEMS

QUESTION PERIOD (maximum 3 minutes per speaker and maximum time allotted 15 minutes)
 - Limited to items on the agenda

12. ADJOURNMENT

Please note: Should this meeting end sooner than 7:00 p.m., the next meeting may start no later than 10 minutes after adjournment of this meeting.

| | 5 |
|---|----|
| | 7 |
| | 10 |
| | 15 |
| | 19 |
| ſ | 28 |

Page #

3

This

Page

is

Intentionally

Left

Blank



| TO: | Chief Administrative Officer |
|----------|------------------------------|
| SUBJECT: | WTP update |
| DATE: | March 13, 2020 |

FROM: Superintendent, Public Works and Engineering Services

Current Status:

- Blind flanges at the North Shore Road and River Road need to be capped to prevent the release of untreated water in the distribution network.
 - River road was completed on the 12th-Mar.
 - Northshore will start on the 16th-Mar.
- River road capping on River Road was straight forward. Contractor had easy access to valve.



Picture shows completed blocking and capping on River Road

- North Shore capping is not straight forward. When contractor investigated the valve, there was significant water infiltration and the clay subsurface made ground conditions very unstable.
- Contractor will have to use two vactor trucks to continuously haul away muddy water. The construction hole will take up the entire lane. Water interruption notices have be sent to all affected houses.
- Stantec is scheduled to be onsite on the 16th-Mar to continue commissioning.
- Tritech will be onsite at the same time on the 16th-Mar to address outstanding deficiencies.
- Was expecting to receive a proposal form a new 3rd party Level 4 Operator. Due to a loss of resource from contractor. PWS is looking for another resource.
 - Operator's duties would include: monthly walk-through and inspection of the WTP with written reports of the walk-through to be submitted to VIHA..
- Water from the WTP is currently running through the filters (without coagulation chemicals), UV and chlorine systems.

Kam So, P.Eng, MBA (Candidate) Superintendent, Public Works and Engineering Services





| TO: | Chief Administrative Officer |
|----------|---|
| SUBJECT: | Summary Report for PWS – Feb 2020/Mar 2020 |
| DATE: | March 13, 2020 |
| FROM: | Superintendent, Public Works and Engineering Services |

Asset Management Plan

- Asset Management Project
 - Progress meeting with consultant conducted on 20th-Feb.
 - o Next step consultant working towards final report.

Capital Projects

- River Road Boaster Station Upgrade
 - o 95% design submitted for review.
 - o External Fire Pumps with diesel back-up is required for flow capacity.
 - o Received updated cost estimate.
 - Waiting for FN response to increase funding.
- Sewage Lagoon Slope Stability
 - Construction tender awarded.
 - Works starts on 16th-Mar-20.
 - o Clearing of site, fencing being taken down.
 - Required silt/safety fencing to prevent deer from entering the lagoon.
- North Shore Water Intake Genset
 - o Received Electrical consultant on site on the 27 "Jan to inspect pump house.
 - o Delivery of genset expected in April.
 - o Awaiting pricing from contractor to install genset.
- WTP See WTP Memo
 - Check valves at WTP and Intake Pump house have been installed.
 - Waterline at River Road has been capped.
 - Work to continue on North Shore Road, to cap water line.
- Green Infrastructure Environmental Quality Sub-Stream Application Grant has been submitted.

- Scoping condition assessment for the eventually replacement of the Pine Street Booster Station.
- Preparing scope of work for Modelling of the Town Sewage System.

Maintenance

- Repaired 3 water leaks;
- All streetlights requests have been submitted to BC Hydro;
- On-going patching of roads.
- Sidewalk repairs as required.

Major Flood Events - None

Power Outages – None

Operations

- PWS crew maintained weekly garbage collection.
- PWS crew contained daily water and wastewater collection.
- Fire hydrate checks conducted.
- PWS crew compiled quarterly Lagoon and Water reports.

Meetings

• Met with several contractors on brush clearing.

Reports

- Submitted recycling study report to Recycle BC.
- Submitted annual Water Consumption report Statistics Canada
- Reviewed and commented on CVRD Watershed Study.
- Submitted Sewage Lagoon information to SLR for Annual Lagoon Report.

Training

• Level 1 First Aid training planned for April.

Safety

- Submitted Emergency Environmental Plan for Environment Canada
 - o Meets the requirements set out by Emergency BC
 - Conducting desk top training with crew.

Kam So, P.Eng, MBA (Candidate) Superintendent, Public Works and Engineering Services





| TO: | Chief Administrative Officer |
|----------|---|
| SUBJECT: | Roads – Capital Plan |
| DATE: | March 12, 2020 |
| FROM: | Superintendent, Public Works and Engineering Services |

Background

A well-maintained road infrastructure is a crucial requirement if economic development, growth and important social benefits are to accrue to the Town of Lake Cowichan. Poorly maintained roads constrain mobility; significantly raise vehicle operating costs, increase accident rates and their associated human and property costs.

Over a period, road surfaces will continue to deteriorate requiring the roads to be repaired. The Town does not have the financial capacity or resources to repair every road at the same time, but fortunately this is not a necessary strategy. The condition of the roads should be classified for type of use and traffic type. The road should be monitored to watch the condition of the surface and forecast when the deterioration will reach a point that resurfacing is required. Budgeting of financial resources to allow for resurfacing to be completed in a timely manner so as to not allow a disruption in service, minimize life cycle costs and fit within the strategy of the Town's asset management plan.

Strategy for Town road prioritization

- 1. Collector Roads should be given priority over local roads. Minimum threshold of condition of Collector Roads should be higher than for local roads.
- 2. High density traffic areas should be given priority over lower density traffic areas.
- 3. Roads deteriorate exponentially with heavier vehicle traffic. Use of heavy vehicles on local roads should be minimized. Repair of roads with heavy weight vehicle traffic should be prioritized.
- 4. Resurfacing of roads should be timed at the same time as repairs of water mains, sewage or storm lines is undertaken.
- 5. Roads should not deteriorate to the point of needing re-construction.
- 6. Preventative maintenance activities should be utilized to extend the life of the asset.

There is no official criterion on what condition a road can deteriorate to before the road needs resurfacing. But a good strategy is to extend the life of a road with preventative maintenance activities such as fixing potholes, filling of cracks and avoid the use of heavy traffic. Resurface of a road must occur before the point of needing a full reconstruction.

Some local roads may not need resurfacing for decades. An issue with local residential roads is that cars drive too fast. A local road with minor deterioration is a natural speed suppressant for vehicles.

| Suggested | Road | Prioritization | |
|-----------|------|----------------|--|
| | | | |

| Road | Start | Finish | Type of Road | Lengt h | Reason for Priority | Estimated Price Construction Only | Suggested Planned Year |
|---------------------|---------------------|------------------|-----------------|------------|---|--|------------------------------|
| North Shore Road | Round a bout | Wilson Road | Collector | 250 m | Main arterial road. Poor condition. Major project. | 180,000 | 2020-21 |
| River Road | North Shore Rd | Indian Road | Local | 300 m | Road is deflecting. Pavement alligator cracking. | 216,000 | 2020 |
| Greendale Rd. | Cowichan Lake Rd | Town Limit | Local | 800 m | Road is poor condition. To be put in after the sewage line is complete. | 576,000 | 2023 |
| Stone Rd | South Shore Road | Alder Road | Local | 300 m | Cracking and beginning to deteriorate | 216,000 | 2021 |
| Wilson Rd | North Shore Rd | Grosskleg Way | Local | 70 m | Road is cracking. Heave machinery route. Busy route. | 50,400 | 2021 |
| Stone Rd | Hemlock Entrance | | Local | 20 m | Heavy cracking. Steep incline. | 14,400 | 2021 |
| Stone Rd | Fir Entrance | | Local | 20 m | Heavy cracking. Steep incline. | 14,400 | 2021 |
| Boundary Rd | Lot 48 | Comiaken Ave | Local | 150 m | Need for width expansion due to Lot 48 development. | 108,000 | 2021 |
| Johel Rd | At turn in Road | Kwassin Cres | Local | 60 m | No sub-base. Poor condition will deteriorate quickly. | 43,200 | 2021 |

| Future Plans | | | | | | | |
|---------------------|-------------|---------------|-----------|------|--|---------|------|
| King George | South Shore | Round- | Callector | 250 | High profile road. | 190.000 | 2022 |
| St | Road | about | Collector | m | Beginning to crack. | 100,000 | 2022 |
| North Shore Road | Wilson St | Town limit | Collector | 1 km | Road is cracking. Clay sub- base will continue to deflect. Increased traffic due to FN Development. | 720,000 | 2022 |

.



For discussion

The suggested road prioritization is an asset strategy that would greatly improve the Town's road network gradually and does not allow for significant service interruptions.

The cost estimate is for resurfacing of a standard 9m wide road at \$720 lane per meter. Costs do not include design, project management, curbs, sidewalks or sub-base.

Appendix A

Map of suggested prioritization



Kam So, P.Eng, MBA (Canadiate) Superintendent, Public Works and Engineering Services





TO: Chief Administrative Officer

SUBJECT: Sidewalk Capital Plan

DATE: March 13, 2020

FROM: Superintendent, Public Works and Engineering Services

Background

Sidewalks play an important role in transportation, as they provide a safe path for people to walk along that is separated from the motorized traffic. They aid road safety by minimizing interaction between the pedestrians and motorized traffic.

Overtime sidewalks deteriorate, break and warp. Walking paths will need to be readjusted to allow for pedestrians to be uninhibited.

The MMCD standard width of sidewalk on an urban collector road (North Shore, King George, Sahtlam, South Shore, Cowichan Lake Rd) is 1.8 meters. The standard of an urban local road (every other road in town) is a width of 1.5 meters.

When a sidewalk is too narrow, pedestrians cannot walk side by side. It becomes a tripping hazard. Or pedestrians or scooters would just choose to walk on the road, as seen in the below picture.

Although there are some newer sections of sidewalk that are the standard 1.5 meter width, many sections are only 1.2 m in width.



Pedestrians choosing to walk on the roads rather than the sidewalks.

Suggested Sidewalk Strategy

- 1. Pedestrians need a complete path that will connect the length of their desired route. Walking paths should form a complete trail.
- 2. Sidewalks deteriorate over time. Sidewalks that are in need of repair should be repaired.
- 3. The absence of sidewalks can post hazards from narrow roads. Prioritize sidewalks where there is a hazard.
- 4. Existing sidewalks that are too narrow are unusable and a safety hazard.
- 5. Sidewalks should be prioritized in busy walking traffic areas such as downtown or areas close to downtown.

Sidewalk capital plan list

See Appendix A – Side Walks Capital Plan.

Discussion

The Side Walk program can be gradually completed over a number of years. Other strategies of prioritizing sidewalks would be rank areas of population density, new versus replacement, safety or any combination.

No sidewalks are better than broken sidewalks. An option could be to remove sections of sidewalk if they are not going to be addressed. Removing impervious sections of sidewalks will be better for storm drainage.

Steps to creation of Sidewalk Plan

- 1. Decide on a prioritization strategy.
- 2. Verify that all potential section sidewalk projects are on list.
- 3. Determine a yearly budget.
- 4. Rank sidewalk sections in order of council priority.
- 5. Complete projects that are budgeted for 2020.
- 6. Re-evaluate project list next year for changes in priority and adjusting sidewalk conditions.



Conclusion

The estimate for a unit meter length of sidewalk can vary between \$70 per meter to \$160 per meter.

A high level estimate of a budget of \$100,000 for 5 years will restore and bring up to MMCD standards all the deficient sidewalks in town to like new conditions.

Kam So, P.Eng, MBA (Candidate) Superintendent, Public Works and Engineering Services



| | | | | | | <u> </u> | | | Estimated | Estimated | Estimated | Suggested Year. |
|----|------------------|-----------------------|-------------------|--------|-------|----------|----------|---------------------------|-----------|-----------|-----------|--------------------|
| # | Street Name | From | То | Length | Width | In | Priority | Reason | Cost | Cost | Cost | Based on \$100,000 |
| " | Officer Humo | | | (m) | (m) | Service | - | | (\$70/m) | (\$100/m) | (\$150/m) | a year at \$70/m |
| 1 | Park Rd | North Shore Rd. | River Rd. | 300 | 1.22 | 1960 | Н | High Traffic Area | 21000 | 30000 | 45000 | 2020 |
| 2 | River Rd | Park Rd. | North Shore Rd. | 100 | 1.22 | 1980 | Н | Safety, Hill | 7000 | 10000 | 15000 | 2020 |
| 3 | River Rd | North Shore Rd | Elk Rd. | 200 | 1.50 | 1980 | Н | Safety, Hill | 14000 | 20000 | 30000 | 2020 |
| 4 | North Shore Rd. | Wilson Rd. | South Shore Rd. | 400 | 1.50 | 1990 | Н | High Traffic Area | 28000 | 40000 | 60000 | 2020 |
| 5 | Stone Ave. | South Shore Rd. | Stevens Cres. | 500 | 1.22 | 1985 | Н | High Traffic Area | 35000 | 50000 | 75000 | 2020 |
| 6 | Stone Ave. | Stevens Cres. | Sahtlam Ave. | 70 | 1.22 | 1985 | Н | High Traffic Area | 4900 | 7000 | 10500 | 2021 |
| 7 | Stone Ave. | North of Stevens Cres | Ravine to Hemlock | 180 | 1.22 | 2009 | Н | High Traffic Area | 12600 | 18000 | 27000 | 2021 |
| 8 | Fir St. | Stone Ave. | Larch St. | 55 | 1.22 | 1950 | Н | Bad Condition | 3850 | 5500 | 8250 | 2021 |
| 9 | Larch St. | Fir St. | Hemlock St. | 100 | 1.22 | 1950 | Н | Bad Condition | 7000 | 10000 | 15000 | 2021 |
| 10 | Larch St. | Hemlock St. | Arbutus St. E. | 76 | 1.22 | 1950 | H | Bad Condition | 5320 | 7600 | 11400 | 2021 |
| 11 | Arbutus St. | Larch St. | Alder St. | 300 | 1.22 | 1950 | Н | Bad Condition | 21000 | 30000 | 45000 | 2021 |
| 12 | Alder St. | Stone Ave. | Arbutus St. W. | 39 | 1.22 | 1950 | Н | Bad Condition | 2730 | 3900 | 5850 | 2021 |
| 13 | Cowichan Ave. | South Shore Rd. | Coronation St. | 400 | 1.22 | 1950 | H | High Traffic Area . | 28000 | 40000 | 60000 | 2021 |
| 14 | Cowichan Ave. | Coronation St. | King George St. | 94 | 1.22 | 1950 | Н | High Traffic Area | 6580 | 9400 | 14100 | 2021 |
| 15 | Coronation St. | Cowichan Ave. W. | Nelson Rd. W. | 74 | 1.22 | 1970 | Н | High Traffic Area | 5180 | 7400 | 11100 | 2021 |
| 16 | Wellington Rd. | Nelson Rd. W. | Riverside Dr. | 339 | 1.22 | 1998 | H | High Traffic Area | 23730 | 33900 | 50850 | 2022 |
| | | | | | | | | Crowded Area/Remove | | | | |
| 17 | Riverside Dr. | Wellington Rd. | King George St. | 227 | 1.22 | 2008 | Н | curb | 15890 | 22700 | 34050 | 2022 |
| 18 | Renfrew Ave. | King George St. | Coronation St. | 100 | 1.22 | 1975 | <u>н</u> | High Traffic Area | 7000 | 10000 | 15000 | 2022 |
| 19 | Coronation St. | Renfrew Ave. | South Shore Rd. | 91 | 1.22 | 1970 | Н | High Traffic Area | 6370 | 9100 | 13650 | 2022 |
| 20 | Coronation St. | Renfrew Ave. | Lakeview Ave. | 77 | 1.22 | 2016 | Н | High Traffic Area | 5390 | 7700 | 11550 | 2022 |
| 21 | Lakeview Ave. | Coronation St. | King George St. | 100 | 1.22 | 1990 | <u> </u> | High Traffic Area | 7000 | 10000 | 15000 | 2022 |
| 22 | King George St. | South Shore Rd. | Cowichan Ave. | 218 | 1.22 | 1990 | H | High Traffic Area | 15260 | 21800 | 32700 | 2022 |
| 23 | Sahtlam Ave. | Roundabout | Poplar St. | 100 | 1.22 | 1982 | H | High Traffic Area | 7000 | 10000 | 15000 | 2022 |
| 24 | Poplar St. | Sahtlam Ave. | Cowichan Ave. | 33 | 1.22 | 1950 | <u> </u> | No existing sidewalk | 2310 | 3300 | 4950 | 2022 |
| 25 | Sahtlam Ave. | Poplar St. | Pine St. | 143 | 1.50 | 1982 | Н | Bad Condition | 10010 | 14300 | 21450 | 2022 |
| 26 | Grants Lake Rd. | Somenos St. | Natara Place | 254 | 1.22 | 1992 | Н | Difficult Vehicle Traffic | 17780 | 25400 | 38100 | 2023 |
| 27 | Grants Lake Rd. | Somenos St. | Natara Place | 60 | 1.50 | 1992 | Н | Difficult Vehicle Traffic | 4200 | 6000 | 9000 | 2023 |
| 28 | Cowichan Ave, E. | Roundabout | Poplar St. | 88 | 1.22 | 1950 | Н | Old Sections only | 6160 | 8800 | 13200 | 2023 |
| 29 | Cowichan Ave, E. | Poplar St. | Pine St. | 146 | 1.50 | 1950 | Н | Bad Condition | 10220 | 14600 | 21900 | 2023 |
| 30 | Cowichan Ave. E. | Pine St. | Cottonwood St. | 145 | 1.22 | 1950 | Н | Bad Condition | 10150 | 14500 | 21750 | 2023 |
| 31 | Cowichan Ave. E. | Cottonwood St. | Somenos St. | 146 | 1.22 | 1950 | Н | Bad Condition | 10220 | 14600 | 21900 | 2023 |
| 32 | Somenos St. | Sahtlam Ave. | Cowichan Ave. E. | 80 | 1.22 | 1950 | Н | Bad Condition | 5600 | 8000 | 12000 | 2023 |
| 33 | Somenos St. | Cowichan Ave. E. | Quamichan Ave. | 77 | 1.22 | 1950 | Н | Bad Condition | 5390 | 7700 | 11550 | 2023 |
| 34 | Somenos St. | Quamichan Ave. | Nitinat Ave. | 81 | 1.22 | 1950 | Н | Bad Condition | 5670 | 8100 | 12150 | 2023 |
| 35 | Quamichan Ave. | Cottonwood St. | Somenos St. | 145 | 1.22 | 1990 | H | No existing sidewalk | 10150 | 14500 | 21750 | 2023 |
| 36 | Quamichan Ave. | Somenos St. | Boundary Rd. | 46 | 1.22 | 1995 | H | No existing sidewalk | 3220 | 4600 | 6900 | 2023 |
| 37 | Boundary Rd. | Cowichan Ave. E. | Quamichan Ave. | 67 | 1.22 | 1995 | Н | No existing sidewalk | 4690 | 6700 | 10050 | 2023 |
| 38 | Cowichan Ave. E. | Somenos St. | Boundary Rd. | 20 | 1.22 | 1950 | H | No existing sidewalk | 1400 | 2000 | 3000 | 2023 |
| 39 | Cottonwood St. | Quamichan Ave. | Nitinat Ave. | 77 | 1.22 | 1950 | H | Bad Condition | 5390 | 7700 | 11550 | 2023 |
| 40 | Centennial Hall | | | 66 | 1.22 | 1950 | H H | High Traffic Area | 4620 | 6600 | 9900 | 2024 |
| 41 | Sall Rd. | South Shore Rd. | end | 100 | 1.22 | 1975 | L | Low Traffic Area | 7000 | 10000 | 15000 | 2024 |
| 42 | Johel Rd. | #147 Johel Rd. | Kwassin Cres. | 67 | 1.50 | 1970 | L | Bad Condition | 4690 | 6700 | 10050 | 2024 |
| 43 | Johel Rd. | Kwassin Cres. | Chappell Cres. | 41 | 1.50 | 1970 | L | Bad Condition | 2870 | 4100 | 6150 | 2024 |
| 44 | MacDonald Rd. | 110-140 MacDonald | | 43 | 1.22 | 2009 | M | Moderate Traffic Area | 3010 | 4300 | 6450 | 2024 |
| 45 | MacDonald Rd. | Cowichan Lk. Rd. | Oak Lane | 200 | 1.22 | 1965 | M | Moderate Traffic Area | 14000 | 20000 | 30000 | 2024 |
| 46 | MacDonald Rd. | Oak Lane | end | 100 | 1.22 | 1965 | M | Moderate Traffic Area | 7000 | 10000 | 15000 | 2024 |
| 47 | Neva Rd. | Cowichan Lk. Rd. | Oak Lane | 200 | 1.22 | 1980 | M | Moderate Traffic Area | 14000 | 20000 | | |

| 48 | Neva Rd. | Oak Lane | Madill Rd | 200 | 1 22 | 1080 | M | Modorato Traffic Area | 11000 | 00000 | T | |
|--------|----------------|------------------|----------------|-------|------|------|-----|-----------------------|-------|-------|-------|------|
| 49 | Cottonwood St | Sabtlam Ave | Cowieben Ave | 200 | 1.22 | 1000 | | Moderate franc Area | 14000 | 20000 | 30000 | 2024 |
| 50 | Cettermood OL | Oaman Ave. | Cowicitan Ave. | 30 | 1.22 | 1950 | M | Old Sections only | 2100 | 3000 | 4500 | 2024 |
| 50 | Cottonwood St. | Sahtlam Ave. | Comiaken Ave. | 78 | 1.22 | 1950 | М | Bad Condition | 5460 | 7800 | 11700 | 2024 |
| 51 | Boundary Rd. | Comiaken Ave. | end | 185 | 1.22 | 1995 | М | Bad Condition | 12050 | 1000 | 07750 | 2024 |
| 52 | Comiaken Ave. | Boundary Rd. | Cottonwood St | 138 | 1 22 | 1085 | N/1 | Bad Condition | 12900 | 18500 | 27750 | 2024 |
| 53 | Comiakan Avo | Cottonwood St | Disc Of | - 100 | 1.22 | 1905 | IVI | Bad Condition | 9660 | 13800 | 20700 | 2024 |
| | Connaken Ave. | Collonwood St. | Pine St. | 140 | 1.22 | 1985 | M | Bad Condition | 9800 | 14000 | 21000 | 2025 |
| 54 | Cottonwood St. | Cowichan Ave. E. | Quamichan Ave. | 60 | 1.22 | 1950 | M | Not to standard | 4200 | 6000 | 0000 | 2025 |
| 55 | Nitinat Ave. | Cottonwood St | Somenos St | 154 | 1 22 | 1000 | 5.4 | Ded Oscaliti | 42.00 | 6000 | 9000 | 2025 |
| h.vl., | | | Contentos OL | 1.04 | 1.22 | 1992 | IVI | Bad Condition | 10780 | 15400 | 23100 | 2025 |
| | | | | | | | | | | | | |
| | | | | | | | | j- | | | 1 | |

Total Length 8,280

Total Cost

\$528,500 \$755,000 \$1,132,500



| TO: | Chief Administrative Officer |
|----------|---|
| SUBJECT: | South Shore Bus Shelter Replacement |
| DATE: | March 13, 2020 |
| FROM: | Superintendent, Public Works and Engineering Services |

Background

Bus stops are an access point for travellers using BC Transit services. While they can be a positive feature of transit travel, they are often cited as a barrier to transit use due to poor quality shelters, inadequate lighting or other design and infrastructure characteristics.

In a recent market analysis, shelters at bus stops were among the top five enhancements needed to encourage new riders to transit who are currently using other modes of travel.

Historically the selection of shelter design and functionality has been led by the municipality for which the service is being provided. As such, a broad variety of manufacturers and designs have been utilized, and no set standardization methodology or procurement strategy employed (Figure 1)



Figure 1. Bus Shelter on South Shore Road.

Issues with South Shore Road bus shelter:

- Mobility issues from scooters being blocked by the benches.
- Roof is too high and does not adequately protect users from the rain.
- No place for signage.
- Not clearly marked as a bus stop.
- Aging structure in need to rehabilitation.
- Does not use existing land features to optimize accessibility.
- Sharp drop off behind the bus shelter.
- Replacement parts need to be custom made.



Figure 2. Example of a standard Bus Shelter on Cowichan Lake Road is a metal Tara Type 3 Shelter (2011). The company is no longer in business.

BC Transit

Municipalities can access to provincial capital funding in order to purchase standardized shelters for use in their communities.

There are currently three bus shelters in town. The two shelters pictured above and one more in front of the legion.





BC Transit Shelters - Overview of Costs T-Series

Typical BASE costs* for each type of shelter (not including taxes);



Figure 2: the appropriate replacement size for the North Shore Bus Shelter is the Type 3 Series.

Under the capital upgrade program, the bus shelters are <u>owned by BC Transit</u> as assets in order to facilitate the capitalization of costs and allow for cost sharing with participants. Provincial cost sharing for shelter purchases under the Bus Stop Program will follow the standard contribution agreement for capital projects.

Provincial Share: 46.7% Municipal Share: 53.3%

The municipality is responsible for any civil and electrical work required to prepare a site for shelter installation. This includes the funding and construction of any infrastructure such as, but not limited to, bus pads or engineered foundations, pullouts, sidewalk construction, and electrical grid connections where required.

Municipalities, through their acceptance and willing participation in this program, agree to maintain the BC Transit shelters in accordance with standard industry practice.



This maintenance, funded 100% by the municipality includes (but is not limited to) the following regular maintenance items:

- Removal of snow and ice when required
- Removal of garbage
- Prompt removal of graffiti
- General cleaning (power washing) of structure on a regular basis
- Soft clean solar roof panels and remove debris monthly
- Monitoring and replacement of damaged components in a timely manner

Recommendations

- 1. Apply for funding through the BC Transit Shelter Program for a Type 3 Shelter. Cost of shelter \$19,213. Not including site prep.
- 2. Remove existing South Shore Bus Shelter.
- 3. Install new bus shelter at the back of the bus loop. See picture below



Kam So, P.Eng, MBA (Candidate) Superintendent, Public Works and Engineering Services





| TO: | Chief Administrative Officer |
|----------|---|
| SUBJECT: | Sewer Plan 2020 |
| DATE: | March 13, 2020 |
| FROM: | Superintendent, Public Works and Engineering Services |

Background

A sanitary sewer is an underground system for transporting sewage from houses and commercial buildings within Lake Cowichan to the town sewage lagoon for treatment and disposal.

Sanitary sewer overflow can occur due to blocked or broken sewer lines, infiltration of excessive stormwater or malfunction of pumps. In these cases untreated sewage is discharged from a sanitary sewer into the environment prior to reaching sewage lagoon. To avoid this, constant maintenance is required.

The maintenance requirements vary with the type of sanitary sewer. In general, all sewers deteriorate with age, and with age infiltration and inflow are problems leading to increased operating costs at the sewage lagoon and often results in overflows to the environment. Holding infiltration to acceptable levels requires a high standard of maintenance. A comprehensive construction inspection program is required to prevent inappropriate connection of cellar, yard, and roof drains to sanitary sewers. The probability of inappropriate connections is higher where sewers and sanitary sewers are found in close proximity, because construction personnel may not recognize the difference.

For decades, when sanitary sewer pipes cracked or experienced other damage, the only option was an expensive excavation, removal and replacement of the damaged pipe, typically requiring street repavement afterwards. Today, there are other methods than only External Point Repairs that allow for internal repairs like epoxy resin to re-line aging or damaged pipes, effectively creating a "pipe in a pipe".

Pipeline Assessment

The town has accessed each sewer pipe and was given a rating that reflects the priority and need for maintenance. Table 1, provides a description of the potential implications of the rating.

Table 1.

| Rating | Typical Structural Defects | Typical O&M Defects | Grade Description |
|--------|--|--|-----------------------|
| 5 | Broken/Hole >= 3 Clock Positions Broken/Hole (with soil/voids visible) Collapse Deformed > 10% diameter | Infilration Gusher Deposits > 30% of cross section Root balls in mainline | Most significant |
| 4 | Multiple Fractures Broken and 1 clock Position Hole and 1 clock Positions Deformed <= 10% diameter | Infiltration Runner Deposits <= 30% of cross section Medium roots in mainline | Significant |
| 3 | Multiple Cracks Logitudinal and Spiral Fractures | Infiltration Dripper Deposits <=20% of cross section Tap Roots in mainline Medium roots in lateral | Moderate |
| 2 | Logitudinal Crack, Spiral Crack Circumferential Fractures Large Joint Offset of Seperation | Infiltration Weeper Deposits <=10% of cross section Roots fine in mainline Tap roots in lateral Defective lateral | Minior to Moderate |
| 1 | Minor | | Minor |

Overall Condition of Sewage System

| | | | Custom Pipe | e Rating | | | |
|------------------|----------------------------------|----------------------|-------------|----------|-----|-----|-----|
| Diameter (mm) | Total Length Inspected (m) | MH to MH Segments | 5 | 4 | 3 | 2 | 1 |
| 150 | 228 | 5 | 0 | 0 | 0 | 0 | 5 |
| 200 | 14119 | 196 | 5 | 6 | 20 | 36 | 129 |
| 250 | 1512 | 19 | 0 | 0 | 6 | 5 | 8 |
| Total | 15859 | 220 | 5 | 6 | 26 | 41 | 142 |
| L | | | 2% | 3% | 12% | 19% | 64% |



Overall, 83% of all pipe segments are found to be in good condition; where 142 of the pipe segments (64%) showed minimal to no defects, and 41 of the pipe segments (19%) contained defects that were considered minor to moderate. These pipe segments generally do not require maintenance. If maintenance is required it is minor, such as grease cutting or debris removal.

Of the 37 pipe segments (17% overall) that had a pipe rating of 3 or greater, 5 had severe defects (rating 5) and 6 had moderate to severe defects (rating 4). These pipe segments require more intensive maintenance, including root cutting, grouting, trenchless point repairs, and external point repairs.

Sewage rehabilitation strategy

- 1. Inflow and Infiltration is causing issues with overflow at the sewage lagoon. There is an order from the Ministry of the Environment and Climate Change that the town needs to address the overflow.
- 2. Pipes with a grade description of 1-3 do not need to be addressed right away, but they will soon become 4-5 and the costs to repair will become higher.
- 3. Address the suggested repairs in order of significance.
- 4. Every year, re-evaluate the list and continue with projects in priority.

Suggested order of rehabilitation

See Appendix A.

Kam So, P.Eng, MBA (Candidate) Superintendent, Public Works and Engineering Services



22

.

.

.

Town of Lake Cowichan Water Inventory

| | ln | | F | Pipe Length | n (meters) | | |
|------------------|---------|------|-----------|-------------|------------|-------|-----------|
| Street Name | Service | 50mm |)mm 100mm | 150mm | 200mm | 250mm | 345 mm |
| 1 11 12 | Date | 2″ | 4" | 6″ | 8" | 10" | 12" |
| Indian Road | | | | | | | 300 |
| River Rd | 1980 | | | 80 | 240 | 650 | |
| Alder St | 1950 | | | 64 | | | |
| Arbutus St | 1950 | | | 41.8 | | | |
| Carnell Drive | | | | 54.8 | | | |
| Cedar Ave. | 1950 | | | | 103.8 | | |
| Centennial Park | 2015 | | | | 350 | | |
| Cowichan Avenue | 1950 | | | 155 | | | |
| Elk Rd | 1980 | | | 100 | 280 | | |
| Fern Rd | 1983 | | | 180 | 200 | | |
| Fir Lane | 1950 | | | 88.6 | | | |
| Grants Lake Road | 1950 | | | 579 | 102 | | |
| Greendale Rd | 1950 | 630 | 180 | | | | |
| Hemlock St | 1950 | | | 145.3 | | | |
| Larch St | 1950 | | | 220 | | | |
| MacDonald Rd | 1965 | | | 550 | | | |
| Nelson Road East | 1950 | | | | 65 | | |
| Nelson Road East | 1950 | | | 96 | | | |
| Neva Rd | 1980 | | | 420 | | | |
| Oak Lane | 1965 | | | 120 | | | |
| South Shore Road | 2012 | | | | 20 | | |
| Stone Ave | 1950 | | | 221 | | | |
| Beaver Rd | 1989 | | | 390 | | | |
| Beech Crescent | 2007 | | | 265 | | | |
| Berar Rd | 1975 | | 190 | | • | | |
| Boundary Rd | 1950 | | 290 | | | | |
| Castley Heights | 1992 | | | | | 310 | |
| Chappell Cres | 1981 | | | 65 | | | |
| Comiaken Ave | 1985 | | | 360 | | | |
| Coronation St N | 1970 | | | 150 | | | |
| Cottonwood St. | 1950 | | 180 | | | | |
| Darnell Rd | 1950 | | 250 | | | | |
| Deer Rd | 1975 | | 240 | | ······ | | |
| Eldred Rd | 1974 | | 280 | | | | |
| Gordon Rd | 1950 | 180 | | | | | |
| Hillside Rd | 1977 | | 80 | | | | |
| Johel Road | 1970 | | | 400 | | | |
| King George St | 1950 | | | 50 | | | |

2018 (3).xls

22

Town of Lake Cowichan Water Inventory

| | In | Pipe Length (meters) | | | | | |
|-----------------|---------|----------------------|-------|-------|-------|-------|-----------|
| Street Name | Service | 50mm | 100mm | 150mm | 200mm | 250mm | 345 mm |
| | Date | 2″ | 4" | 6″ | 8″ | 10" | |
| Lake Park Road | 1994 | | | | 210 | | |
| Lakeview Rd | 1950 | | 20 | 240 | | | |
| Maple Ave. | 1950 | | 120 | | | | |
| Natara Place | 1950 | | | 100 | | | |
| Nitnat Ave | 1950 | | | 170 | | | |
| Nootka Cres | 1975 | | 60 | | | | |
| North Shore Rd | 1950 | | | | 450 | 860 | |
| Park Rd | 1960 | | | 300 | | | |
| Peterson Rd. | 2002 | 50 | | | | | |
| Pine Street new | 1950 | | | | 180 | | |
| Poplar St | 1950 | | 110 | | | | |
| Prospect Ave. | 1950 | | 500 | | | | |
| Quamichan | 1950 | | | | 250 | | |
| Quamichan Ave | 1950 | | | | 400 | | |
| Renfrew Ave | 1975 | 150 | | | 110 | | |
| Riverside Dr | 1950 | | 40 | 210 | | | |
| Rockland Rd | 1950 | 100 | | | | | |
| Sahtlam Ave | 1950 | | 320 | 500 | | | |
| Sall Rd | 1975 | | | 150 | | | |
| Savoy Rd | 1978 | | 240 | | | | |
| Scholey Cres | 1991 | | 100 | | | | |
| Somenos | 1950 | | 20 | 450 | | | |
| Stanley Rd | 1950 | | 220 | | | | |
| Stevens Cres | 1950 | 35 | 90 | | | | |
| Tern Rd New | 1975 | | 250 | | | | |
| Wellington Rd | 1950 | 80 | 160 | | | 150 | |
| Wilson Rd | 1975 | | | 250 | | | _ |
| | | | | | | | |
| | Total | 1,225 | 3,940 | 6,922 | 2,521 | 1,320 | - |

C:\Users\joseph.LAKECOWICHAN\AppData\Local\Microsoft\Windows\INetCache\Content.Outlook\OJVFWQJR\Copy of TCA Water system inventory 2/ 2 2018 (3).xls

| Order of Priority | Pipe Segment | Pipe Rating | 1&1 | Recommended Rehabilitation | Est Cost |
|----------------------|--------------|----------------|-----|--|----------|
| 1 | B15 - B4A | 5 | Yes | External Point Repair for Hole Soil Visible @ 48.1 m | 18000 |
| 2 | F24 - F23 | 5 | Yes | Trenchless Point Repair for Hole Soil Visible @ 43.6 m | 4800 |
| 3 | J5A - J5 | 5 | Yes | 1. External Point Repair for pipe sag @ 26.1 m | 40100 |
| | | | | 2. Trenchless Point Repair @ 32.1 m US, Root cut and reinspect | |
| | | | | to confirm rehabilitation method | |
| | | | | 3. Trenchless Point Repair @ 30.4 m DS, Root cut and reinspect | |
| | | | | to confirm rehabilitation method | |
| 4 | B24 - B5 | 5 | Yes | 1. External Point Repair for Hole from 41.5 m | 22800 |
| | | | | 2. Trenchless Point Repair for Roots Fine Joint @ 71.4 m | |
| 5 | E53 - E52 | 5 | Yes | 1. Trenchless Point Repair for Hole (Soil Visible) @ 66.3 m US | 8400 |
| | | Ū | | and reinstate service connection | 0.000 |
| 6 | S25B S25 | 5 | No | External Point Repair, Re-Inspect | 4700 |
| 7 | D24 - D21 | 5 | Yes | Grouting, Trenchless Point Repair, Re-Inspect, Cut Crease | 5700 |
| 8 | SC06 - S25 | 5 | No | External Point Repair | 14300 |
| 9 | D25 - D24 | 5 | No | Cut Crease, Root Cutting, Grouting, Trenchless Point repair. | 5700 |
| 10 | F1 - 1D1 | 4 | Yes | 1. Cut Grease @ 7.6 m | 5800 |
| • | | | | 2. Trenchless Point Repair @ 7.6 m, reinspect after CG to | |
| | | | | confirm rehabilitation method | |
| | | | | 3. Cut Grease @ 45.7 m | |
| 11 | E41 - E33 | 4 | Yes | 1. Root Cut and Trenchless Point Repair @ 26.7 m and | 17700 |
| | | | | Reinstate Service Connection | |
| | | | | 2. Trenchless Point Repair for Surface Aggregate Missing @ | |
| | | | | 00.5 []] 1. Tranchlass Daint Panair far broken ning @ 21.5 m and | |
| 12 | G3 - G2 | 4 | Yes | I. Trenchiess Form Repair for broken pipe @ 21.5 m and Beinstate Service Connection | 8400 |
| 13 | S25 - S24 | 4 | No | Root Cutting, Re-Inspect | 600 |
| 14 | S28 - S27 | 4 | No | Remove Debris, External Point of Repair | 9500 |
| 15 | SC06B - S25B | 4 | No | Reline, Root Cut, Re-Inspect | 51,400 |
| 16 | D19 - D18 | 4 | No | External Point Repair | 4500 |
| 17 | D23 - D22 | 4 | No | External Point Repair | 5400 |
| 18 | J4 - J1 | 4 | Yes | 1. Grout Infil Runner - Manhole/Sewer interface @ 94.2 m | 3600 |
| 19 | E39 - E37 | 4 | Yes | 1. Grout Infil Runner inside MH E37 Barrel @ 85.9 m | 3600 |
| 20 | F19 - F15 | 4 | No | 1. Cut Intruding Service | 13500 |
| | | | | 2. Trenchless Point Repair @ 38.9 m and Reinstate Service | |
| | | | | Connections, Root cut and reinspect to confirm rehabilitation | |
| | | | | method | |
| 21 | E3 - E2 | 3 | Yes | 1. Trenchless Point Repair for broken pipe @ 22 m | 4800 |
| 22 | F16 - F15 | 3 | Yes | 1. Trenchless Point Repair for Hole - LEAKING @ 81.9 m | 4800 |
| 23 | H15 - H13 | 3 | Yes | 1. Trenchless Point Repair for Hole @ 10.9 m | 4800 |
| 24 | F14 - F4 | 3 | Yes | Service Connections | 4800 |
| 25 | | 2 | | 1. Trenchless Point Repair for Crack and Infil staining @ 62.45 | 1000 |
| 25 | A6 - A5 | 3 | res | m | 4800 |
| 26 | B8 - B7 | 3 | No | 1. Trenchless Point Repair @ 46m DS of MH B8, reinspect to | 9300 |
| 27 | C20 - C19 | 3 | No | 1 Root Cutting for Roots Fine Joint @ 44.7 m | 9400 |
| <i>L1</i> | 020 013 | 5 | 140 | 2. Trenchless Point Renair @ 46 m | 3400 |
| | | | | 3. Cut Grease @ 46 m US | |
| 28 | A13 - A6 | 3 | No | 1. External Point Repair for Joint Offset Large @ 1 m | 36000 |
| | | 3 | | 2. External Point Repair for Joint Offset Large @ 18.6 m | |
| 29 | A9 - A2 | 3 | Yes | 1. Grout Infil Runner from 12 o'clock @ 42.2 m | 7200 |
| | | | | 2. Grout Infil Stain from 4 o'clock @ 46.1 m | |
| 30 | H2 - H1 | 3 | Yes | 1. Grout Tap Break-in Capped - WITH ROCKS@ 19.3 m | 3600 |

| 31 | C12 - C8 | 3 | Yes | Cut Intruding Service Tap Break-in Intruding @ 90.6 m and Reinstate Service Connections Grout Infil Stain @ 117.2 m | 4800 |
|------|-------------|---|-----|--|-------|
| 32 | E40 - E39 | 3 | Yes | 1. Trenchless Point Repair for Roots Fine Barrel @ 62.9 m | 4800 |
| 33 | E49 - E44 | 3 | Yes | 1. Trenchless Point Repair for AGGREGATE CHIPPED AND SEEPING @ 55.6 m | 4800 |
| 34 | D4 - D3 | 3 | No | 1. Cut Grease from 40 m to 50.0 m | 900 |
| 35 | B10 - B9 | 3 | No | 1. External Point Repair for Tap Break-in Defective @ 29.2 m | 20400 |
| 36 | C3 - C2 | 3 | No | 1. Trenchless Point Repair for Surface Aggregate Projecting - CONCRETE IS Flaking at Join from 9 o'clock @41.9 m | 5400 |
| 37 | 1A1 - 2A1 | 3 | No | 1. Cut Grease from 6.0 m to 12.0 m | 900 |
| 38 | G1 - 1D1 | 3 | No | 1. Cut Grease @ 29.2 m | 4800 |
| 39 | | | | 2. Root Cutting for Roots Fine Joint @ 33.3 m | |
| 40 | E21-E20 | 3 | No | 1. Cut Grease @ 74.2 m | 900 |
| 41 | D13 - D12 | 3 | No | Cut Crease | 500 |
| 42 | E50 - E49 | 3 | No | Cut Crease, External Point Repair | 4900 |
| 43 | D14 - D13 | 3 | No | Cut Crease | 300 |
| 44 | S9 - S8 | 3 | No | External Point Repair | 5400 |
| 45 | SC7 - S20 | 3 | No | External Point Repair | 5200 |
| 46 | D8 - D9C | 3 | No | Re-Inspect | 400 |
| 47 | D6 - D5 | 3 | Yes | Re-Inspect | 900 |
| 48 | D41 - D17 | 3 | No | Re-Inspect | 400 |
| 49 | K1 - D9A | 3 | No | Re-Inspect | 400 |
| 50 | D9A - D9B | 3 | No | Re-Inspect | 400 |
| 51 | D9C - D7 | 3 | No | Re-Inspect | 500 |
| 52 | D7 - D6 | 3 | No | Re-Inspect | 600 |
| 53 | S24 - S23 | 2 | Yes | Trenchless Point Repair | 3800 |
| · 54 | K3 - K2 | 2 | Yes | Cut Crease, Grouting | 1500 |
| 55 | D46 - D5 | 2 | No | Grouting | 1100 |
| 56 | S20 - S22 | 2 | No | Remove Debris | 400 |
| 57 | D5 - D4 | 2 | No | Re-Inspect | 600 |
| 58 | E52 - E44 | 2 | No | 1. Trenchless Point Repair for Infil Stain @ 93.3 m | 4800 |
| 59 | C22 - C6A | 2 | No | 1. Remove Deposits Settled Gravel @ 67.5 m | 900 |
| 60 | J1 - E22 | 2 | No | 1. Cut Grease @13.1 m | 900 |
| 61 | E42 - E34 | 2 | No | 1. Cut Grease @ 81.7 m | 900 |
| 62 | E34 - E33 | 2 | No | No 1. Cut Grease @ 46.1 m | 500 |
| 63 | A20C - A20B | 2 | No | 1. Root Cutting and Grout for Roots Fine Joint @ 46.5 m | 500 |

Table 5-3: Recommended Rehabilitation on Public Property based on Smoke Testing Results

Detections from Downspout

| D1 | C28B | C28A | External Point Repair | 5000 |
|-----|-------|-------|-----------------------|-------|
| A9 | C28A | C28A | External Point Repair | 5000 |
| | | | | |
| A5 | A20E | A20D | Replace IC Cap | 300 |
| B3 | E9 | E8 | Replace IC Cap | 300 |
| B8 | A22 | A21 | Replace IC Cap | 300 |
| A2 | F18 | F17 | Replace IC Cap | 300 |
| D4 | C13 | C12 | Replace IC Cap | . 300 |
| A10 | C2A | C28A | Replace IC Cap | 300 |
| A4 | H5 | H4 | Replace IC Cap | 300 |
| C2 | A3 | A2 | Replace IC Cap | 300 |
| A3 | F7 | F6 | Replace IC Cap | 300 |
| | | | | 500 |
| A3 | D31 | D30 | Replace IC Cap | 200 |
| A4 | K7 | K6 | Replace IC Cap | 300 |
| B8 | S15 | S14 | Replace IC Can | 300 |
| A2 | SC06B | \$25B | Renlace IC Can | 300 |
| | 22000 | 5250 | neplace ic cap | 300 |

| B7 | D35 | D34 | External Point Repair | 1000 |
|-----|-------|------|-----------------------|--------|
| B3 | SC4 | S16 | External Point Repair | 4000 |
| B4 | D30 | D29 | External Point Repair | 4000 |
| B5 | D32 | D10 | External Point Repair | 4000 |
| B1 | E50 | E49 | External Point Repair | 4000 |
| A6 | K5 | K4 | External Point Repair | 4000 |
| A7 | K6 | K5 | External Point Repair | - 4000 |
| A5 | К7 | К6 | External Point Repair | 4000 |
| B6 | К8 | K7 | External Point Repair | 4000 |
| C1. | S8 | S7 | External Point Repair | 4000 |
| B2 | S8 | S7 | External Point Repair | 4000 |
| A1 | S9 | S8 | External Point Repair | 4000 |
| C2 | SC06B | S25B | External Point Repair | 4000 |
| | | | | |



| то: | Chief Administrative Officer |
|----------|---|
| SUBJECT: | Town Water Distribution Network. |
| DATE: | March 13, 2020 |
| FROM: | Superintendent, Public Works and Engineering Services |

Background

The Town's distribution network consists of watermains that are underground pipes that deliver a steady supply of fresh, clean drinking water to residents and businesses.

The Town has approximately 22.3 km of various sizes from 50 mm to 250 mm in diameter.

The original watermains in town were put into service in 1950.

The correct size of watermain will allow water to be delivered to residents at the proper flow and at the proper demand.

Sizing the system

To determine the required diameter size of watermain, the amount of water flow required must be established. It would be easiest turn on all the fixtures in an area and add up their flow rates, and using the total for system demand. However, the likelihood of all fixtures being in operation simultaneously is negligible.

System demand is assigned by estimating the population and occupancy type of an area.

With the system demand calculation a water model is created to provide a preliminary judgment on the required main water line size. This figure is adjusted later if the chosen size produces excessive pressure loss.

Since 1950, the population of the town has been growing and there is a need to increase the diameter size of many sections watermains due to a an increasing loss in hydraulic and fire flow capacity.

Some sections of pipe also need to be repaired due to mineral deposits clogging in the inside of the pipes leading to poor water pressure and increased line breakages. Constantly repairing the same line, will eventually lead to a catastrophic service disruption.

Status of Town's Watermains

There are two watermains that need to be increased to allow for proper Hydraulic capacity for the town. 300 m on Indian Road and 1000 m on River Road.

20 other areas are needed to increase the size of the watermains to allow for proper fire flow protection.

The remaining water lines have been installed in 1950 and are past their expected lifespan. Pipes that are beyond 70 years old could have mineral deposits that lessen water flow are more susceptible to line breakages. These lines do not necessarily need to be replaced immediately, but should be continuously monitored.

Status of Town's other water infrastructure

The Intake Pump House on North Shore road will need replacing in 10 years. The booster station at Neva Road needs an additional fire pump.

There are projects on the go already that address the fire flow issues at the River Road Pressure Zone and the Slopes Pressure Zone.

Town Water Main Strategy

- 1. Increase sizing of watermains that meet town water hydraulic capacity.
- 2. Increase sizing of watermians that meet town fire flow capacity.
- 3. Replace watermains that are not performing at their design capacity.
- 4. Replace watermains that have continuous service disruptions.

Discussion

The watermains on Indian Road and River Road are the only water lines leaving the WTP. It is imperative that these water lines meet the hydraulic design capacity. Estimated cost \$317,500.

The 6.4 km of pipe upsizing for the fire flow can be gradually improved over several years. Estimated total cost \$1,166,575.

The remaining system that was installed in 1950 can be scheduled to be replaced in 5-10 years. Estimated total cost \$2,831,250.

The cost was calculated by using \$250/m for just Pipe and Backfill. .

Kam So, P.Eng, MBA (Candidate) Superintendent, Public Works and Engineering Services

